


*Typ3 osa*

# Universal Milling Cycles



Edition

# 101

*Typ3 osa*

# Universal Milling Cycles

1070 073 795-101 (99.07) GB



© 1999

by Robert Bosch GmbH, Erbach / Germany  
All rights reserved, including applications for protective rights.  
Reproduction or handing over to third parties are subject to our written permission.

Discretionary charge 10.00 DM

# Table of Contents

	Page
<b>1</b>	<b>Safety Instructions</b> . . . . . <b>1–1</b>
1.1	Proper use . . . . . 1–1
1.2	Qualified personnel . . . . . 1–3
1.3	Safety markings on products . . . . . 1–4
1.4	Safety instructions in this manual . . . . . 1–4
1.5	Safety instructions concerning the product described . . . . . 1–5
1.6	Dokumentation, Version und Warenzeichen . . . . . 1–7
<b>2</b>	<b>Special Features</b> . . . . . <b>2–1</b>
<b>3</b>	<b>Definitions</b> . . . . . <b>3–1</b>
3.1	Roughing/Finishing . . . . . 3–1
3.1.1	Combined . . . . . 3–1
3.1.2	Roughing . . . . . 3–1
3.1.3	Finishing . . . . . 3–1
3.2	Centre Point . . . . . 3–2
3.2.1	Plane G17 . . . . . 3–2
3.2.2	Plane G18 . . . . . 3–2
3.2.3	Plane G19 . . . . . 3–2
3.3	Feed . . . . . 3–3
3.3.1	Drilling Feed . . . . . 3–3
3.3.2	Roughing Feed . . . . . 3–3
3.3.3	Finishing Feed . . . . . 3–3
3.3.4	Milling Feed . . . . . 3–3
3.4	Infeed Plane . . . . . 3–4
3.5	Depth . . . . . 3–5
3.6	Max. Depth per Revolution . . . . . 3–6
3.7	Length/Width . . . . . 3–7
3.7.1	Rectangular Pocket/Inside Frame . . . . . 3–7
3.7.2	Groove . . . . . 3–7
3.7.3	Outside Frame . . . . . 3–7
3.8	Corner Radius . . . . . 3–8
3.8.1	Rectangular Pocket/Inside Frame . . . . . 3–8
3.8.2	Rectangular Pocket/Outside Frame . . . . . 3–8
3.9	Angle . . . . . 3–9
3.9.1	Groove . . . . . 3–9
3.9.2	Rectangular Pocket, Inside Frame/Outside Frame . . . . . 3–9
3.10	Diameter . . . . . 3–10
3.10.1	Circular Pocket/Borehole . . . . . 3–10
3.10.2	Tenon . . . . . 3–10
3.10.3	End Groove, Inside Diameter/Outside Diameter . . . . . 3–10
3.10.4	Inside Circle Segment . . . . . 3–11
3.10.5	Outside Circle Segment . . . . . 3–11
3.11	Direction of Rotation . . . . . 3–12
3.11.1	Down/Up Milling . . . . . 3–12
3.11.2	Direction of Rotation during Mirroring . . . . . 3–13
3.12	Finishing Overmeasure/Wall . . . . . 3–14
3.12.1	Circular Pocket . . . . . 3–14
3.12.2	Rectangular Pocket . . . . . 3–14

3.12.3	Groove .....	3-14
3.13	Finishing Overmeasure/Base .....	3-15
3.13.1	Circular Pocket .....	3-15
3.13.2	Rectangular Pocket .....	3-15
3.13.3	Groove .....	3-15
3.14	Blank Overmeasure .....	3-16
3.14.1	Circular Pocket .....	3-16
3.14.2	Rectangular Pocket .....	3-16
3.14.3	Groove .....	3-16
3.15	Starting Angle .....	3-17
3.15.1	End Groove .....	3-17
3.15.2	Inside Circle Segment .....	3-17
3.15.3	Outside Circle Segment .....	3-17
3.15.4	Borehole .....	3-18
3.15.5	Tenon .....	3-18
3.15.6	Inside Frame .....	3-19
3.15.7	Tenon (Frame) .....	3-19
3.16	Approach Radius .....	3-20
3.16.1	Borehole .....	3-20
3.16.2	Tenon .....	3-20
3.16.3	Inside Frame .....	3-21
3.16.4	Outside Frame .....	3-21
3.16.5	Inside Circle Segment .....	3-22
3.16.6	Outside Circle Segment .....	3-22
3.17	Milling Angle .....	3-23
3.17.1	Inside Circle Segment .....	3-23
3.17.2	Outside Circle Segment .....	3-23
3.18	In-position Programming .....	3-24
3.19	Return to Starting Point .....	3-24
<b>4</b>	<b>Program Preconditions .....</b>	<b>4-1</b>
4.1	Tool .....	4-1
4.2	Cutter Radius .....	4-1
4.3	Cutter Compensation .....	4-1
4.4	Spindle Speed .....	4-1
4.5	Spindle Direction of Rotation .....	4-1
4.6	Scale Factor .....	4-1
4.7	Milling Plane .....	4-1
4.8	Infeed Axis and Direction .....	4-1
<b>5</b>	<b>Description of cycles .....</b>	<b>5-1</b>
5.1	Menu Overview .....	5-1
5.1.1	Main Menu .....	5-1
5.1.2	Pocket Milling Cycle Menu .....	5-2
5.1.3	Contour Milling Cycle Menu .....	5-3
5.2	Pocket Milling Cycles .....	5-4
5.2.1	Rectangular Pocket .....	5-4
5.2.2	Circular Pocket .....	5-6
5.2.3	Groove .....	5-8
5.2.4	End Groove .....	5-10
5.3	Contour Milling Cycles .....	5-12
5.3.1	Inside Frame .....	5-12
5.3.2	Outside Frame .....	5-14
5.3.3	Borehole .....	5-16
5.3.4	Inside Circle Segment .....	5-18
5.3.5	Outside Circle Segment .....	5-20
5.3.6	Tenon .....	5-22

<b>6</b>	<b>Technology parameters</b> .....	<b>6-1</b>
6.1	Overlap Factor (#CCVL) .....	6-1
6.2	Safety Clearance (#CCVS) .....	6-2
6.2.1	Reverse Rapid Traverse .....	6-2
6.2.2	Partial Retraction .....	6-2
6.3	Wall Clearance during Base Finishing (#CCVW) .....	6-3
6.4	Base Clearance during Wall Finishing (#CCVB) .....	6-3
<b>7</b>	<b>Installing the machine cycles</b> .....	<b>7-1</b>
7.1	Installation .....	7-1
7.2	Installed programs .....	7-2
7.3	Adaption of MACODA datas .....	7-4
7.4	Troubleshooting .....	7-6
<b>A</b>	<b>Appendix</b> .....	<b>A-1</b>
A.1	Index .....	A-1



# 1 Safety Instructions

Before you start working with the “Universal milling cycles” we recommend that you thoroughly familiarize yourself with the contents of this manual. Store this manual in a place to which all users have access at any time.

## 1.1 Proper use

This documentation contains information required for the proper use of the control unit. For reasons of clarity, however, it cannot contain all detail about all possible combinations of functions. Likewise, as the control unit is usually part of a larger installation or system, it is impossible to consider every conceivable case of integration, programming or operation.


The Typ3 osa is used to

- activate feed drives, spindles and auxiliary axes of a machine tool via SERCOS interface for the purpose of guiding a processing tool along a programmed path to machine a workpiece (CNC). Furthermore, a PLC is required with appropriate I/O components which – in communication with the actual CNC – controls the machine processing cycles holistically and acts as a technical safety monitor.
- program contours and the machining technology (path feedrate, spindle speed, tool change) of a workpiece.

Any other application is deemed improper use!

The product described

- has been developed, manufactured, tested and documented in compliance with the safety standards. This product poses no danger to persons or property if it is used in accordance with the handling regulations and safety notes prescribed for its configuration, installation and proper operation.
- complies with the requirements of
  - the EMC Directives (89/336/EEC, 93/68/EEC and 93/44/EEC)
  - the Low-Voltage Directive (73/23/EEC)
  - the harmonized standards EN 50081-2 and EN 50082-2
- is designed for operation in industrial environments (emission class A), i.e.
  - no direct connection to public low-voltage power supply,
  - connection to the medium- or high-voltage system via a transformer.In residential environments, in trade and commerce as well as small enterprises class A equipment may only be used if it does not inadmissibly interfere with other equipment.

 **This is a class A device which may cause radio interference in residential environments. In this case, the operator may be required to take suitable countermeasures and to bear the cost of the same.**

The faultless, safe functioning of the product presupposes proper transport, storage, erection and installation as well as careful operation.

**CAUTION**

This product as well as our operating, programming, visualization and control software have been examined for "Year 2000 compliance" and have passed the required tests.

Please note that the "Year 2000 compliance" may be lost if additional software packages are installed, and that any such event would be the customer's responsibility.

Examples for the possible loss of the "Year 2000 compliance" known to us include:

1. If other software packages are installed, some of the software components supplied by us may be overwritten (e.g. DLL's).
2. The additionally installed software may read the date directly from the BIOS or even from the time module. To correct the date after the turn of the millennium it will be sufficient to restart the unit.
3. Some components of Microsoft products (e.g. the File Manager and the Explorer) have limited "Year 2000 compliance" capabilities. More information is available on the World Wide Web pages of Microsoft at <http://www.eu.microsoft.com/ithome/topics/year2k/product/product.htm> .



## 1.2 Qualified personnel

The requirements as to qualified personnel depend on the qualification profiles described by ZVEI (central association of the electrical industry) and VDMA (association of German machine and plant builders) in:

**Weiterbildung in der Automatisierungstechnik**

**edited by: ZVEI and VDMA**

**MaschinenbauVerlag**

**Postfach 71 08 64**

**D-60498 Frankfurt.**

The present manual is designed for NC programming personnel and NC project engineers.

Programming, start and operation as well as the modification of programs or program parameters may only be performed by properly trained personnel! This personnel must be able to judge potential hazards arising from programming, program changes and in general from the mechanical, electrical, or electronic equipment.

The programming of the control unit may enable you to influence axis movements (e.g. positions, etc.), machining technology (e.g. feed, speed, etc.) and the machining process (e.g. tool change, compensations, issuing of auxiliary functions, etc.).

All this presupposes firstly a general knowledge of programming (e.g. for the logical program sequence, etc.) and, secondly, knowledge of the technology of the process to be performed.

Unauthorized interference in the program code or ignoring warning signs attached to the components, or non-compliance with the warning notes given in this manual may result in serious bodily injury or material damage.

Only technicians who are familiar with the contents of this manual may compile programs or adapt existing programs.

Such personnel are

- those who, being well trained and experienced in their field and familiar with the relevant standards, are able to analyze the work to be carried out and recognize any hazards.
- those who have acquired the same amount of expert knowledge through years of experience that would normally be acquired through formal technical training.

Please note our comprehensive range of training courses.

Our training center will be pleased to provide you with further information, telephone: +49 (0) 6062 78-258.

### 1.3 Safety markings on products



Warning of dangerous electrical voltage!



Warning of danger caused by batteries!



Components sensitive to electrostatic discharge!



Disconnect from mains before opening!



Pin for connecting PE conductor only!



Connection of shield conductor only

### 1.4 Safety instructions in this manual




#### **DANGER**

This symbol is used wherever an insufficient or lacking compliance with instructions can result in **personal injury**.



#### **CAUTION**

This symbol is used wherever an insufficient or lacking compliance with instructions can result in **damage to equipment or data files**.

 This symbol is used to inform the user of special features.

★ This symbol is used if user activities are required.

## 1.5 Safety instructions concerning the product described

---

**DANGER**

**Danger of death due to inadequate EMERGENCY-STOP devices!**  
**EMERGENCY-STOP devices must be active and within reach in all system modes. Releasing an EMERGENCY-STOP device must not result in an uncontrolled restart of the system!**  
**First check the EMERGENCY-STOP circuit, then switch the system on!**

---

**DANGER**

**Incorrect or undesired axis movement!**  
**First, new programs should be tested carefully without axis movement! For this purpose, the control unit offers the possibility of inhibiting axis movements and/or auxiliary function outputs by appropriate softkeys in the “automatic“ group operating mode.**

---

**DANGER**

**Tool or axis movements!**  
**Feed and spindle motors generate very powerful mechanical forces and can accelerate very quickly due to their high dynamics.**

- **Always stay outside the danger area of the machine when it is running!**
- **Do not ever deactivate the safety-relevant functions of the unit!**
- **Report any malfunction of the unit to your servicing and repairs department immediately!**

---

**CAUTION**

**Only spare parts approved by Bosch may be used!**

---

**CAUTION**

**Danger to the module!**  
**All ESD protection measures must be observed when using the module! Prevent electrostatic discharges!**

---

The following protective measures must be observed for modules and components sensitive to electrostatic discharge (ESD)!

- The personnel responsible for storage, transport, and handling must have been trained for ESD protection.
- ESD-sensitive components must be stored and transported in their prescribed protective packaging.
- ESD-sensitive components may only be handled at special ESD-workplaces.

- Personnel, working surfaces, as well as all equipment and tools which get in contact with ESD-sensitive components must have the same potential (e.g., by grounding).
- Wear an approved grounding bracelet. The grounding bracelet must be connected with the working surface through a cable with an integrated resistor of 1 M $\Omega$ .
- ESD-sensitive components must by no means get in contact with chargeable objects, including most plastic materials.
- When ESD-sensitive components are installed in or removed from equipment, the equipment must be de-energized.

## 1.6 Dokumentation, Version und Warenzeichen

### Documentation

The present manual provides information about programming "Universal Milling Cycles".

Overview of available documentation	Part no.	
	German	English
Interface conditions for project engineering and maintenance	1070 073 704	1070 073 736
Operating instructions Standard operator interface	1070 073 726	1070 073 739
Operating instructions – Diagnostics Tools	1070 073 779	1070 073 780
DIN programming instructions for programming to DIN 66025	1070 073 725	1070 073 738
CPL programming instructions	1070 073 727	1070 073 740
ICL700 system description, program structure of the integrated PLC	1070 073 706	1070 073 737
ICL700 project planning manual, software interfaces and CNC interface signals of the integrated PLC	1070 073 728	1070 073 741
MACODA operation and configuration of the machine parameters	1070 073 705	1070 073 742
Tool Management Parameter Setting	1070 073 782	–
Software PLC Development Environment for Windows NT	1070 073 783	1070 073 792
Measuring cycles for touch-trigger switching probes	1070 073 788	1070 073 789
Universal Milling Cycles	–	1070 073 795

### Version

- ☞ **This manual refers to the following product version:  
Software: V4.3.16**
- ☞ **The current release number of the individual software modules can be viewed by selecting the "Control-Diagnostics" softkey in the "Diagnostics" group operating mode.**
- ☞ **The software version of Windows 95 or Windows NT may be displayed as follows:**
  1. **Click with right mouse key on the "My Computer" icon on your desktop**
  2. **Select menu item "Properties".**

### Modifications

Modifications in the present manual as compared to the previous edition are marked by black vertical bars in the margin.



This symbol is used in illustrations to call your attention to any modifications made.

## Trademarks

All trademarks of software installed on Bosch products upon delivery are the property of the respective manufacturer.

Upon delivery, all installed software is copyright-protected. The software may only be reproduced with the approval of Bosch or in accordance with the license agreement of the respective manufacturer.

MS-DOS® and Windows™ are registered trademarks of Microsoft® Corporation.

## 2 Special Features

Material is removed in the pocket cycles by following contours. For pre-machined workpieces, a blank overmeasure can be defined so that you can machine without empty movements by beginning at a certain distance from the pocket centre rather than from the pocket centre itself.

The pocket can be machined clockwise or counter-clockwise (direction of rotation of the tool) in the pocket cycles. This means that both down milling and up milling are possible, depending on the direction of rotation of the spindle.

The direction of rotation of the tool can be chosen differently for roughing and for finishing.

The pocket cycles can be used as separate or combined roughing/finishing cycles, controlled by an execution parameter. Different finishing overmeasures can be specified for the wall and base.

The milling cycles are invoked without active tool path compensation because the active tool radius is offset internally in the cycles.

All infeed movements in rapid traverse maintain a safety clearance of 1mm. This value appears on a solid background in the cycles, and can be changed by modifying the value assigned to the #CCVS parameter in the P999999100 subroutine.

When base finishing, the finishing tool – for technological reasons – does not touch the wall that has already been roughed. The value for this wall clearance (0.01mm) appears on a solid background in the cycles, and can be changed by modifying the value assigned to the #CCVW parameter in the P999999100 subroutine.

After base finishing, i.e. before wall finishing, the finishing tool is retracted for technological reasons. The value for this base clearance (0.01mm) appears on a solid background in the cycles, and can be changed by modifying the value assigned to the #CCVB parameter in the P999999100 subroutine.

An overlap of at least 10% is maintained in the pocket cycles. This value appears on a solid background in the cycles, and can be changed by modifying the value assigned to the #CCVL parameter in the P999999101 subroutine.

**Deactivation conditions:**

At the end of the cycle, the following conditions apply for all milling cycles:

- The tool is located, with spindle rotating, at safety clearance above the infeed plane.
- Rapid traverse GO is active.
- The last feed programmed in the milling cycle is active.
- Depending on the situation before the cycle is invoked, either absolute dimension (G90) or incremental dimension (G91) is active.
- The polar plane corresponds to the milling plane, with the pole in the centre of the pocket.

**Variable assignment:**

All global variables used in the cycles begin with the letters "#CC".

Do not use this combination of letters to begin variables in your own CPL programs.



## 3 Definitions

### 3.1 Roughing/Finishing

#### 3.1.1 Combined


Combined means:

One single tool does the following in succession:

- roughing
- base finishing and
- wall finishing.

This parameter is only active in the following cycles:

- rectangular pocket
- circular pocket and
- groove.



#### 3.1.2 Roughing


Roughing means:

The tool performs roughing only.

This parameter value lets you rough and finish in separate steps using different tools.

This parameter is only active in the following cycles:

- rectangular pocket
- circular pocket and
- groove.



#### 3.1.3 Finishing


Finishing means:

The tool performs finishing only.

This parameter value lets you rough and finish in separate steps using different tools.

This parameter is only active in the following cycles:

- rectangular pocket
- circular pocket and
- groove.



## 3.2 Centre Point

### 3.2.1 Plane G17


Milling plane: X/Y (centre point)

Infeed plane: Z (drilling axis)

The centre point dimensions specify, for each axis, the distance between the workpiece centre and the axis datum.

The dialogue screen automatically switches to the associated infeed plane when you choose the infeed axis.

The parameter values are entered as absolute dimensions (in mm).



### 3.2.2 Plane G18


Milling plane: Z/X (centre point)

Infeed plane: Y (drilling axis)

The centre point dimensions specify, for each axis, the distance between the workpiece centre and the axis datum.

The dialogue screen automatically switches to the associated infeed plane when you choose the infeed axis.

The parameter values are entered as absolute dimensions (in mm).



### 3.2.3 Plane G19


Milling plane: Y/Z (centre point)

Infeed plane: X (drilling axis)

The centre point dimensions specify, for each axis, the distance between the workpiece centre and the axis datum.

The dialogue screen automatically switches to the associated infeed plane when you choose the infeed axis.

The parameter values are entered as absolute dimensions (in mm).



### 3.3 Feed

#### 3.3.1 Drilling Feed

The drilling feed acts along the drilling axis.

The drilling feed is only active in the following cycles:

- rectangular pocket
- circular pocket
- groove and
- end groove.

Input in mm/min.

#### 3.3.2 Roughing Feed

The roughing feed acts on the milling plane.

The roughing feed is only active during roughing in the following cycles:

- rectangular pocket
- circular pocket and
- groove.

Input in mm/min.

#### 3.3.3 Finishing Feed

The finishing feed acts on the milling plane.

The finishing feed is only active during finishing in the following cycles:

- rectangular pocket
- circular pocket and
- groove.

Input in mm/min.


#### 3.3.4 Milling Feed

The milling feed acts on the milling plane.

The milling feed is only active during milling in the following cycles:

- end groove
- borehole
- inside frame
- outside frame
- tenon
- inside circle segment and
- outside circle segment.

Input in mm/min.



### 3.4 Infeed Plane

The Infeed Plane parameter corresponds to the top edge of the workpiece.



The variable value is entered as an absolute dimension (in mm).

Positive and negative values are allowed.

When approaching the infeed plane, a safety clearance is automatically maintained.

(defined as #CCVS in the P999999100 cycle – see TECHNOLOGY PARAMETERS)

The infeed axis switches from rapid traverse to drilling feed when it is the safety clearance away from the infeed plane.



### 3.5 Depth

The Depth parameter specifies the final dimension of the pocket base in the cycles:

- rectangular pocket
- circular pocket and
- groove.

The depth parameter specifies the height in the cycles:

- end groove
- borehole
- inside frame and
- inside circle segment.



The depth is counted in negative direction starting from the infeed plane.

The parameter value is entered as an incremental dimension (in mm). Only positive values are allowed.

The infeed axis and infeed direction are switched over using G78.

The milling plane is selected using G17 or G18, or G19 or G220.

(The X/Y level appears on a solid background by default.)





### 3.6 Max. Depth per Revolution

The Max. Depth per Revolution parameter specifies the maximum depth infeed that is allowed in any one cutter revolution.

The effective depth infeed is the result of even cut distribution combined with maximum infeed depth.

Only positive parameter values (in mm) are allowed.

The parameter is active in all cycles, both roughing and finishing.



## 3.7 Length/Width


### 3.7.1 Rectangular Pocket/ Inside Frame

These parameters determine the length and width of the rectangular pocket and inside frame.

(Finished dimension)

The cycle monitors to determine if the width is greater than the length.

The parameter values are entered as incremental dimensions (in mm). Only positive values are allowed.




### 3.7.2 Groove

These parameters determine the length and width of the groove.

(Finished dimension)

The parameter values are entered as incremental dimensions (in mm). Only positive values are allowed.




### 3.7.3 Outside Frame

These parameters determine the length and width of the outside frame.

(Finished dimension)

The cycle monitors to determine if the width is greater than the length.

The parameter values are entered as incremental dimensions (in mm). Only positive values are allowed.




## 3.8 Corner Radius

### 3.8.1 Rectangular Pocket/ Inside Frame

These parameters determine the length and width of the rectangular pocket and inside frame.  
(Finished dimension)

The cycle monitors to determine if the cutter radius of the selected tool is smaller than the corner radius minus finishing overmeasure.


The parameter values are entered as incremental dimensions (in mm). Only positive values are allowed.



### 3.8.2 Rectangular Pocket/ Outside Frame

This parameter determines the corner radius of the outside frame.  
(Finished dimension)

The parameter value is entered as an incremental dimension (in mm). Only positive values are allowed.






## 3.9 Angle

### 3.9.1 Groove

This parameter is used to rotate the cycle geometry on a plane.

The angle is specified as an absolute value in degrees. (Mathematically positive direction of rotation)

Values can be positive, negative or zero.




### 3.9.2 Rectangular Pocket Inside Frame Outside Frame

These parameters are used to rotate the cycle geometry on a plane.

The angle is specified as an absolute value in degrees. (Mathematically positive direction of rotation)

Values can be positive, negative or zero.




## 3.10 Diameter

### 3.10.1 Circular Pocket/Borehole

These parameters determine the diameter of the circular pocket and borehole.  
(Finished dimension)


The parameter value is entered as an incremental dimension (in mm). Only positive values are allowed.



### 3.10.2 Tenon

This parameter determines the diameter of the tenon.  
(Finished dimension)

The parameter value is entered as an incremental dimension (in mm). Only positive values are allowed.




### 3.10.3 End Groove/ Inside Diameter Outside Diameter

These parameters determine the diameter of the end groove.  
(Finished dimension)

The groove width is half of the diameter difference.


The parameter value is entered as an incremental dimension (in mm). Only positive values are allowed.



### 3.10.4 Inside Circle Segment

This parameter determines the diameter of the inside circle segment.  
(Finished dimension)


The parameter value is entered as an incremental dimension (in mm). Only positive values are allowed.



### 3.10.5 Outside Circle Segment

This parameter determines the diameter of the outside circle segment.  
(Finished dimension)

The parameter value is entered as an incremental dimension (in mm). Only positive values are allowed.



### 3.11 Direction of Rotation

**Direction of Rotation=3**

**Roughing Rotation =3**


**Finishing Rotation =3**

This parameter determines the cutting direction clockwise during machining.

In the cycles:

- rectangular pocket
- circular pocket and
- groove,

a different direction of rotation can be chosen for roughing and finishing. In all other cycles there is only one direction of rotation.



**Direction of Rotation=4**

**Roughing Rotation =4**


**Finishing Rotation =4**

This parameter determines the cutting direction counter-clockwise during machining.

In the cycles:

- rectangular pocket
- circular pocket and
- groove,


a different direction of rotation can be chosen for roughing and finishing. In all other cycles there is only one direction of rotation.



#### 3.11.1 Down/Up Milling

Corresponding to the chosen direction of rotation and the chosen spindle speed, milling is either

- up (conventional) or
- down (climb).




### 3.11.2 Direction of Rotation during Mirroring

The direction of rotation during mirroring is not adapted to the mirrored geometry.

When mirroring about just one axis, up milling becomes down milling and vice versa.

The up or down milling only remains the same when mirroring about two axes.




## 3.12 Finishing Overmeasure/Wall

### 3.12.1 Circular Pocket

The parameter value is entered as an incremental dimension (in mm). Only positive values or zero are allowed.

If you enter zero, finishing continues to the finished dimension, i.e. the wall is not finished.

This also applies when the cycle is invoked with the parameter Roughing/Finishing = 2.




### 3.12.2 Rectangular Pocket

The parameter value is entered as an incremental dimension (in mm). Only positive values or zero are allowed.

If you enter zero, finishing continues to the finished dimension, i.e. the wall is not finished.

This also applies when the cycle is invoked with the parameter Roughing/Finishing = 2.




### 3.12.3 Groove

The parameter value is entered as an incremental dimension (in mm). Only positive values or zero are allowed.

If you enter zero, finishing continues to the finished dimension, i.e. the wall is not finished.

This also applies when the cycle is invoked with the parameter Roughing/Finishing = 2.




### 3.13 Finishing Overmeasure/Base

#### 3.13.1 Circular Pocket

The parameter value is entered as an incremental dimension (in mm). Only positive values or zero are allowed.


If you enter zero, depth finishing continues to the finished dimension, i.e. the base is not finished.



#### 3.13.2 Rectangular Pocket

The parameter value is entered as an incremental dimension (in mm). Only positive values or zero are allowed.


If you enter zero, depth finishing continues to the finished dimension, i.e. the base is not finished.



#### 3.13.3 Groove

The parameter value is entered as an incremental dimension (in mm). Only positive values or zero are allowed.

If you enter zero, depth finishing continues to the finished dimension, i.e. the base is not finished.



## 3.14 Blank Overmeasure

### 3.14.1 Circular Pocket


This parameter is active during both roughing and finishing.

The parameter value is entered as an incremental dimension (in mm) and calculated starting at the centre point. Only positive values and zero are allowed.

Entering zero means machining starts at the centre point.

Maximum value

$\frac{1}{2}$  diameter minus (finishing overmeasure/wall plus cutter radius).



### 3.14.2 Rectangular Pocket


This parameter is active during both roughing and finishing.

The parameter value is entered as an incremental dimension (in mm) and calculated starting at the centre point. Only positive values and zero are allowed.

Entering zero means machining starts at the centre point.

Maximum value

$\frac{1}{2}$  pocket width minus (finishing overmeasure/wall plus cutter radius).



### 3.14.3 Groove


This parameter is active during both roughing and finishing.

The parameter value is entered as an incremental dimension (in mm) and calculated starting at the centre point. Only positive values and zero are allowed.

Entering zero means machining starts at the centre point.

Maximum value

$\frac{1}{2}$  groove width minus (finishing overmeasure/wall plus cutter radius).





## 3.15 Starting Angle


### 3.15.1 End Groove

This parameter determines the position of the starting point for machining.

The starting point is calculated from the inside diameter, half the groove width (computed value) and the starting angle.

The angle is entered as an absolute value in degrees. (Mathematically positive direction of rotation)

Values can be positive, negative or zero.




### 3.15.2 Inside Circle Segment

This parameter determines the contour start and the position of the starting point for machining.

The starting point is calculated from the diameter, the approach radius, the cutter radius and the starting angle.

The angle is entered as an absolute value in degrees. (Mathematically positive direction of rotation)

Values can be positive, negative or zero.




### 3.15.3 Outside Circle Segment

This parameter determines the contour start and the position of the starting point for machining.

The starting point is calculated from the diameter, the approach radius, the cutter radius and the starting angle.

The angle is entered as an absolute value in degrees. (Mathematically positive direction of rotation)

Values can be positive, negative or zero.




### 3.15.4 Borehole

A starting angle of zero degrees is automatically specified in this cycle.

The starting point is calculated from the diameter, the starting angle of zero degrees and the approach radius.


The start is always made from the centre point.



### 3.15.5 Tenon

In this cycle, a starting angle of zero degrees is automatically specified.

The starting point is calculated from the centre point, the diameter, the starting angle of zero degrees and the approach radius.




### 3.15.6 Inside Frame

A starting angle of zero degrees is automatically specified in this cycle.

The starting point is calculated from the centre point, the frame width, the starting angle of zero degrees and the approach radius.

The start is always made from the centre point.




### 3.15.7 Tenon (Frame)

A starting angle of zero degrees is automatically specified in this cycle.

The starting point is calculated from the centre point, the frame width, the starting angle of zero degrees and the approach radius.

The start can be made from any position; the contour is always approached at a tangent.



## 3.16 Approach Radius


### 3.16.1 Borehole

This parameter determines the starting point for machining.

The parameter value is entered as an incremental value (in mm). Only positive values are allowed.

The starting point is calculated from the centre point, the diameter, the starting angle of zero degrees and the approach radius.

The start is always made from the centre point.




### 3.16.2 Tenon

This parameter determines the starting point for machining.

The parameter value is entered as an incremental value (in mm). Only positive values are allowed.

The starting point is calculated from the centre point, the diameter, the starting angle of zero degrees and the approach radius.




### 3.16.3 Inside Frame

This parameter determines the starting point for machining.

The parameter value is entered as an incremental value (in mm). Only positive values are allowed.

The starting point is calculated from the centre point, the frame width, the starting angle of zero degrees and the approach radius.

The start is always made from the centre point.




### 3.16.4 Outside Frame

This parameter determines the starting point for machining.

The parameter value is entered as an incremental value (in mm). Only positive values are allowed.

The starting point is calculated from the centre point, the frame width, the starting angle of zero degrees and the approach radius.

The start can be made from any position; the contour is always approached at a tangent.




### 3.16.5 Inside Circle Segment

This parameter determines the starting point for machining.

The parameter value is entered as an incremental value (in mm). Only positive values are allowed.

The starting point is calculated from the diameter, the approach radius, the cutter radius and the starting angle.




### 3.16.6 Outside Circle Segment

This parameter determines the starting point for machining.

The parameter value is entered as an incremental value (in mm). Only positive values are allowed.

The starting point is calculated from the diameter, the approach radius, the cutter radius and the starting angle.




## 3.17 Milling Angle

### 3.17.1 Inside Circle Segment

This parameter determines the cutting length at the inside circle.


The parameter value is entered as an incremental dimension (in degrees). Only positive values are allowed.



### 3.17.2 Outside Circle Segment

This parameter determines the cutting length at the outside circle.

The parameter value is entered as an incremental dimension (in degrees). Only positive values are allowed.



### 3.18 In-position Programming

#### In-position = 1:


This parameter value causes the axes to be positioned accurately in their end position.  
The position area is defined by machine parameters.

#### In-position = 0

This parameter value extends the positioning area (changing the block "on the fly").

This parameter is only active in the cycles:

- inside frame and outside frame




### 3.19 Return to Starting Point

#### Return to Starting Point = 0 (In G0 Mode):

This parameter value causes the cutter, after completing machining, to retract to the approach plane plus safety clearance and then return in rapid traverse to the starting point.

This parameter is only active in the cycles:

- inside circle segment and outside circle segment.




#### Return to Starting Point = 1 (In G2/G3):

This parameter value causes the cutter, after completing machining, to retract to the approach plane plus safety clearance and then return in a circular movement to the starting point.

This parameter is only active in the cycles:

- inside circle segment and outside circle segment.





## 4 Program Preconditions

### 4.1 Tool

The tool must be selected before the cycle is invoked.

### 4.2 Cutter Radius

The active cutter radius must be defined either by programming the appropriate D geometric compensation group or by activating the compensation values (G145–G845) provided by the PC600.

### 4.3 Cutter Compensation

No cutter compensation G41 or G42 must be active. The cycles calculate the cutter path themselves.

### 4.4 Spindle Speed

The spindle speed must be programmed before the cycle is invoked.

### 4.5 Spindle Direction of Rotation

The spindle direction of rotation must be programmed before the cycle is invoked.

### 4.6 Scale Factor

**No** scale factor must be programmed.

### 4.7 Milling Plane

The plane must be selected using G17, G18, G19 or G20.

### 4.8 Infeed Axis and Direction

The infeed axis and direction with the length compensation offset must be switched over with G78. By default, infeed is in negative direction on the Z-axis (corresponds to machine parameter P6507).


Notes:

## 5 Description of cycles


### 5.1 Menu Overview

#### 5.1.1 Main Menu

The following figure shows the main menu. You can press softkeys to select.



- means: CALL —> menu of **drilling cycles**  
(see Typ3 DIN-Programming documentation)



- means: CALL —> menu of **hole patterns**  
(see Typ3 DIN-Programming documentation)




- means: CALL —> menu of **pocket milling cycles**  
see kap. 5.2



- means: CALL → menu of **contour milling cycles** (see kap. 5.3)




- means: CALL → CPL-program information



- means: **return** → to the next highest dialogue level


## 5.1.2 Pocket Milling Cycle Menu

The following figure shows the pocket milling cycle menu. You can select from the cycles shown in the softkey bar.



### 5.1.3 Contour Milling Cycle Menu

The following figure shows the contour milling cycle menu. You can select from the cycles shown in the softkey bar.




## 5.2 Pocket Milling Cycles

### 5.2.1 Rectangular Pocket


#1:
➔
⊘
11.06.99  
16:46:37

B: Manage/Edit
⏏


## RECTANGULAR POCKET




DRILLING AXIS (1=X, 2=Y, 3=Z)	: Z
MILLING PLANE	: XY = G17
ROUGHING/FINISHING	
0=COMBINED	1
1=ROUGHING ONLY	
2=FINISHING ONLY	
CENTRE POINT INX	100.000
CENTRE POINT INY	100.000
DRILLING FEED	200
ROUGHING FEED	100
FINISHING FEED	100
INFED PLANE	ZE
DEPTH	T
MAX. DEPTH PER REVOLUT.	5.000
LENGTH	L
WIDTH	B
CORNER RADIUS	R
ANGLE	W
ROUGHING ROTAT. (3/4)	3
FINISH. OVERMEAS./WALL	0.100
FINISH. OVERMEAS./BASE	0.200
FINISH. ROTATION (3/4)	4
BLANK OVERMEASURE	0.000




Starting point



Base finishing



Roughing



Wall finishing

## Programming Example

Milling a rectangular pocket with wall finishing.

.		
.		
<b>N101</b>	<b>T1234</b>	Tool number
<b>N102</b>	<b>M6</b>	Tool change
<b>N103</b>	<b>M3 S500</b>	Direction of rotation/speed
<b>N104</b>	<b>GO X0 Y0</b>	Position axes to zero
<b>N105</b>	<b>D1</b>	Call tool number from geometry table (D compensation)
<b>N106</b>	<b>P102</b>	Call rectangular pocket cycle
	<b>[0,</b>	Roughing/finishing combined
	<b>100,</b>	Centre point in X (mm, absolute)
	<b>100,</b>	Centre point in Y (mm, absolute)
	<b>200,</b>	Drilling feed (mm/min)
	<b>1000,</b>	Roughing feed (mm/min)
	<b>1000,</b>	Finishing feed (mm/min)
	<b>0,</b>	Infeed plane (mm, absolute)
	<b>20,</b>	Depth (mm, incremental)
	<b>5,</b>	Maximum depth per revolution (mm, incremental)
	<b>100,</b>	Length (mm, incremental)
	<b>50,</b>	Width (mm, incremental)
	<b>20,</b>	Corner radius (mm, incremental)
	<b>20,</b>	Angle (degrees, absolute)
	<b>3,</b>	Roughing rotation
	<b>0.1,</b>	Finishing overmeasure/wall (mm, incremental)
	<b>0,</b>	Finishing overmeasure/base (mm, incremental)
	<b>4,</b>	Finishing rotation
	<b>0]</b>	Blank overmeasure (mm, incremental)
<b>N107</b>	<b>M5</b>	
<b>etc.</b>		

## Messages / Plausibility

ROUGHING/FINISHING FALSE  
 DRILLING FEED <=0  
 ROUGHING FEED <=0  
 FINISHING FEED <=0  
 DEPTH <=0  
 MAX. INFEEED PER REVOLUTION <=0  
 MAX. INFEEED PER REVOLUTION > DEPTH  
 LENGTH <=0  
 WIDTH <=0  
 CORNER RADIUS <=0  
 FALSE DIRECTION OF ROTATION FINISHING/ROUGHING  
 FINISHING OVERMEASURE/WALL <0  
 FINISHING OVERMEASURE/BASE <0  
 BLANK OVERMEASURE <0  
 ACTIVE CUTTER RADIUS <=0  
 CUTTER RAD. >= ((HALF POCKET WIDTH – WALL OVERMEASURE) \*  
 0.9)  
 CUTTER RADIUS > CORNER RADIUS – WALL OVERMEASURE  
 LENGTH < WIDTH  
 BLANK OVERMEASURE TOO LARGE


5.2.2 Circular Pocket

#1: KANAL1 17.06.99  
 NC: typ3osa 18:36:52



B: Manage/Edit

**CIRCULAR POCKET**


DRILLING AXIS (1=X, 2=Y, 3=Z) : Z  
 MILLING PLANE : XY = G17




ROUGHING/FINISHING	1
0=COMBINED	
1=ROUGHING ONLY	
2=FINISHING ONLY	
CENTRE POINT INX	100.000
CENTRE POINT INY	100.000
DRILLING FEED	200
ROUGHING FEED	1000
FINISHING FEED	1000
INFEEED PLANE	ZE 0.000
DEPTH	T 20.000
MAX.DEPTH PER REVOLUT.	5.000
DIAMETER	D 200.000
ROUGHING ROTAT. (3/4)	3
FINISH. OVERMEAS./WALL	0.100
FINISH. OVERMEAS./BASE	0.200
FINISH. ROTATION (3/4)	4
BLANK OVERMEASURE	■ 0.000



Base finishing



Roughing



Wall finishing



## Programming Example

Milling a circular pocket.

```

.
.
N101   T1234       Tool number
N102   M6          Tool change
N103   M3 S500     Direction of rotation/speed
N104   GO X0 Y0    Position axes to zero
N105   D1          Call tool number from geometry table
                    (D compensation)
N106   P9990103    Call circular pocket cycle
                    [1, Roughing
                    100, Centre point in X (mm, absolute)
                    100, Centre point in Y (mm, absolute)
                    200, Drilling feed (mm/min)
                    1000, Roughing feed (mm/min)
                    0, Finishing feed (mm/min)
                    0, Infeed plane (mm, absolute)
                    20, Depth (mm, incremental)
                    5, Maximum depth per revolution (mm, incremental)
                    200, Diameter (mm, incremental)
                    3, Roughing rotation
                    0.1, Finishing overmeasure/wall (mm, incremental)
                    0, Finishing overmeasure/base (mm, incremental)
                    4, Finishing rotation
                    0] Blank overmeasure (mm, incremental)
N107   M5
etc.

```

## Messages / Plausibility

```

ROUGHING/FINISHING FALSE
DRILLING FEED <=0
ROUGHING FEED <=0
FINISHING FEED <=0
DEPTH <=0
MAX. INFEEED PER REVOLUTION <=0
MAX. INFEEED PER REVOLUTION > DEPTH
DIAMETER <=0
FALSE DIRECTION OF ROTATION FINISHING/ROUGHING
FINISHING OVERMEASURE/WALL <0
FINISHING OVERMEASURE/BASE <0
BLANK OVERMEASURE <0
ACTIVE CUTTER RADIUS <=0
CUTTER RAD. >= ((HALF DIAMETER – WALL OVERMEASURE) * 0.9)
CUTTER RADIUS > CORNER RADIUS – WALL OVERMEASURE
BLANK OVERMEASURE TOO LARGE


```

5.2.3 Groove





#1: 11.06.99  
 NC: typ3osa 16:49:43  
 B: Manage/Edit

**GROOVE**

DRILLING AXIS (1=X, 2=Y, 3=Z) : Z  
 MILLING PLANE : XY = G17



ROUGHING/FINISHING		1
0=COMBINED		
1=ROUGHING ONLY		
2=FINISHING ONLY		
CENTRE POINT INX		100.000
CENTRE POINT INY		100.000
DRILLING FEED		200
ROUGHING FEED		1000
FINISHING FEED		1000
INFEED PLANE	ZE	0.000
DEPTH	T	20.000
MAX. DEPTH PER REVOLUT.		5.000
LENGTH	L	100.000
WIDTH	B	50.000
ANGLE	W	20.000
ROUGHING ROTAT. (3/4)		3
FINISH. OVERMEAS./WALL		0.100
FINISH. OVERMEAS./BASE		0.200
FINISH. ROTATION (3/4)		4
BLANK OVERMEASURE		0.000



## Programming Example

Milling a groove.

```

.
.
N101   T1234       Tool number
N102   M6          Tool change
N103   M3 S500     Direction of rotation/speed
N104   GO X0 Y0    Position axes to zero
N105   D1          Call tool number from geometry table
                    (D compensation)
N106   P9990104    Call groove cycle
                    [2, Finishing
                    100, Centre point in X (mm, absolute)
                    100, Centre point in Y (mm, absolute)
                    200, Drilling feed (mm/min)
                    1000, Roughing feed (mm/min)
                    500, Finishing feed (mm/min)
                    0, Infeed plane (mm, absolute)
                    20, Depth (mm, incremental)
                    5, Maximum depth per revolution (mm, incremental)
                    100, Length (mm, incremental)
                    50, Width (mm, incremental)
                    20, Angle (degrees, absolute)
                    3, Roughing rotation
                    0.1, Finishing overmeasure/wall (mm, incremental)
                    0.1, Finishing overmeasure/base (mm, incremental)
                    4, Finishing rotation
                    0] Blank overmeasure (mm, incremental)
N107   M5
etc.

```

## Messages / Plausibility

```

ROUGHING/FINISHING FALSE
DRILLING FEED <=0
ROUGHING FEED <=0
FINISHING FEED <=0
DEPTH <=0
MAX. INFEEED PER REVOLUTION <=0
MAX. INFEEED PER REVOLUTION > DEPTH
LENGTH <=0
WIDTH <=0
FALSE DIRECTION OF ROTATION FINISHING/ROUGHING
FINISHING OVERMEASURE/WALL <0
FINISHING OVERMEASURE/BASE <0
BLANK OVERMEASURE <0
ACTIVE CUTTER RADIUS <=0
CUTTER RAD. >= ((HALF POCKET WIDTH – WALL OVERMEASURE) *
0.9)
BLANK OVERMEASURE TOO LARGE



```

5.2.4 End Groove

#1: 11.06.99  
 NC: typ3osa 16:55:56  
 B: Manage/Edit

<b>END GROOVE</b>		DRILLING AXIS (1=X, 2=Y, 3=Z) : Z
		MILLING PLANE : XY = G17
	CENTRE POINT INX	100.000
	CENTRE POINT INY	100.000
	DRILLING FEED	100
	MILLING FEED	200
	INFEED PLANE	ZE 0.000
	DEPTH	T 20.000
	MAX. DEPTH PER REVOLUT.	5.000
	OUTSIDE DIAMETER	AD 50.000
	INSIDE DIAMETER	ID 100.000
	ROUGHING ROTAT. (3/4) ON INNER CYRCLE	3
STARTING ANGLE	SW 0.000	

Starting point



Roughing  
or  
finishing

## Programming Example

Milling an end groove.

```

.
.
N101   T1234       Tool number
N102   M6          Tool change
N103   M3 S500     Direction of rotation/speed
N104   GO X0 Y0    Position axes to zero
N105   D1          Call tool number from geometry table
                    (D compensation)
N106   P9990106    Call end groove cycle
                    [100, Centre point in X (mm, absolute)
                    100, Centre point in Y (mm, absolute)
                    300, Drilling feed (mm/min)
                    1000, Milling feed (mm/min)
                    0, Infeed plane (mm, absolute)
                    10, Depth (mm, incremental)
                    10, Maximum depth per revolution (mm, incremental)
                    150, Outer diameter (mm, incremental)
                    100, Inner diameter (mm, incremental)
                    3, Direction of rotation
                    0] Starting angle (degrees, absolute)
N107   M5
etc.

```

## Messages / Plausibility

```

DRILLING FEED <=0
MILLING FEED <=0
DEPTH <=0
MAX. INFEEED PER REVOLUTION <=0
MAX. INFEEED PER REVOLUTION > DEPTH
CUTTER > EFFECTIVE GROOVE WIDTH
INNER DIAMETER >= OUTER DIAMETER
FALSE DIRECTION OF ROTATION
ACTIVE CUTTER RADIUS <=0
INSIDE DIAMETER <=0
OUTSIDE DIAMETER <=0

```

### 5.3 Contour Milling Cycles

#### 5.3.1 Inside Frame

#1:
➔
⊘
11.06.99

NC: typ3osa
➔
⊘
16:58:35

B: Manage/Edit
⏪

<i>INSIDE FRAME</i>		DRILLING AXIS (1=X, 2=Y, 3=Z) : Z																									
		MILLING PLANE : XY = G17																									
	<table style="width: 100%; border-collapse: collapse;"> <tr> <td>CENTRE POINT INX</td> <td style="text-align: right;">100.000</td> </tr> <tr> <td>CENTRE POINT INY</td> <td style="text-align: right;">100.000</td> </tr> <tr> <td>MILLING FEED</td> <td style="text-align: right;">1000</td> </tr> <tr> <td>INFEED PLANE</td> <td style="text-align: right;">ZE 0.000</td> </tr> <tr> <td>DEPTH</td> <td style="text-align: right;">T 20.000</td> </tr> <tr> <td>MAX. DEPTH PER REVOLUT.</td> <td style="text-align: right;">5.000</td> </tr> <tr> <td>LENGTH</td> <td style="text-align: right;">L 100.000</td> </tr> <tr> <td>WIDTH</td> <td style="text-align: right;">B 50.000</td> </tr> <tr> <td>CORNER RADIUS</td> <td style="text-align: right;">R 20.000</td> </tr> <tr> <td>ANGLE</td> <td style="text-align: right;">W 20.000</td> </tr> <tr> <td>ROTATION DIRECT. (3/4)</td> <td style="text-align: right;">3</td> </tr> <tr> <td>APPROACH RADIUS</td> <td style="text-align: right;">AR 20.000</td> </tr> <tr> <td>INPOS PROG. ON/OFF (1/0)</td> <td style="text-align: right;">0</td> </tr> </table>	CENTRE POINT INX	100.000	CENTRE POINT INY	100.000	MILLING FEED	1000	INFEED PLANE	ZE 0.000	DEPTH	T 20.000	MAX. DEPTH PER REVOLUT.	5.000	LENGTH	L 100.000	WIDTH	B 50.000	CORNER RADIUS	R 20.000	ANGLE	W 20.000	ROTATION DIRECT. (3/4)	3	APPROACH RADIUS	AR 20.000	INPOS PROG. ON/OFF (1/0)	0
CENTRE POINT INX	100.000																										
CENTRE POINT INY	100.000																										
MILLING FEED	1000																										
INFEED PLANE	ZE 0.000																										
DEPTH	T 20.000																										
MAX. DEPTH PER REVOLUT.	5.000																										
LENGTH	L 100.000																										
WIDTH	B 50.000																										
CORNER RADIUS	R 20.000																										
ANGLE	W 20.000																										
ROTATION DIRECT. (3/4)	3																										
APPROACH RADIUS	AR 20.000																										
INPOS PROG. ON/OFF (1/0)	0																										
<div style="display: flex; justify-content: space-around; align-items: flex-start;"> <div style="text-align: center;"> <p>Starting point</p> </div> <div style="text-align: center;"> <p>Roughing or finishing</p> </div> </div>																											

## Programming Example

Milling an inside frame.

```

.
.
N101   T1234       Tool number
N102   M6           Tool change
N103   M3 S500     Direction of rotation/speed
N104   GO X0 Y0    Position axes to zero
N105   D1           Call tool number from geometry table
                        (D compensation)
N106   P9990110    Call inside frame cycle
                        100, Centre point in X (mm, absolute)
                        100, Centre point in Y (mm, absolute)
                        500, Milling feed (mm/min)
                        0, Infeed plane (mm, absolute)
                        20, Depth (mm, incremental)
                        5, Maximum depth per revolution (mm, incremental)
                        200, Length (mm, incremental)
                        90, Width (mm, incremental)
                        20, Corner radius (mm, incremental)
                        20, Angle (degrees, absolute)
                        3, Direction of rotation
                        25, Approach radius (mm, incremental)
                        1] In-position programming on
N107   M5
etc.

```

## Messages / Plausibility

```


MILLING FEED <=0
DEPTH <=0
MAX. INFEEED PER REVOLUTION <=0
MAX. INFEEED PER REVOLUTION > DEPTH
LENGTH <=0
WIDTH <=0
CORNER RADIUS <=0
FALSE DIRECTION OF ROTATION
ACTIVE CUTTER RADIUS <=0
CUTTER RAD. >= (HALF POCKET WIDTH * 0.9)
CUTTER RADIUS > CORNER RADIUS
LENGTH < WIDTH
APPROACH RADIUS <= CUTTER RADIUS
APPROACH RADIUS >= HALF WIDTH
IN-POSITION PROGRAMMING FALSE

```


5.3.2 Outside Frame

#1: 11.06.99  
 NC: typ3osa 17:12:29  
 B: Manage/Edit ↩

<i>OUTSIDE FRAME</i>																															
	<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="padding: 2px;">DRILLING AXIS (1=X, 2=Y, 3=Z)</td> <td style="padding: 2px;">: Z</td> </tr> <tr> <td style="padding: 2px;">MILLING PLANE</td> <td style="padding: 2px;">: XY = G17</td> </tr> <tr> <td style="padding: 2px;">CENTRE POINT INX</td> <td style="padding: 2px;">100.000</td> </tr> <tr> <td style="padding: 2px;">CENTRE POINT INY</td> <td style="padding: 2px;">100.000</td> </tr> <tr> <td style="padding: 2px;">MILLING FEED</td> <td style="padding: 2px;">1000</td> </tr> <tr> <td style="padding: 2px;">INFEED PLANE</td> <td style="padding: 2px;">ZE 0.000</td> </tr> <tr> <td style="padding: 2px;">DEPTH</td> <td style="padding: 2px;">T 20.000</td> </tr> <tr> <td style="padding: 2px;">MAX. DEPTH PER REVOLUT.</td> <td style="padding: 2px;">5.000</td> </tr> <tr> <td style="padding: 2px;">LENGTH</td> <td style="padding: 2px;">L 100.000</td> </tr> <tr> <td style="padding: 2px;">WIDTH</td> <td style="padding: 2px;">B 50.000</td> </tr> <tr> <td style="padding: 2px;">CORNER RADIUS</td> <td style="padding: 2px;">R 20.000</td> </tr> <tr> <td style="padding: 2px;">ANGLE</td> <td style="padding: 2px;">W 45.000</td> </tr> <tr> <td style="padding: 2px;">ROTATION DIRECT. (3/4)</td> <td style="padding: 2px;">3</td> </tr> <tr> <td style="padding: 2px;">APPROACH RADIUS</td> <td style="padding: 2px;">AR 20.000</td> </tr> <tr> <td style="padding: 2px;">INPOS PROG.ON/OFF(1/0)</td> <td style="padding: 2px;">0</td> </tr> </table>	DRILLING AXIS (1=X, 2=Y, 3=Z)	: Z	MILLING PLANE	: XY = G17	CENTRE POINT INX	100.000	CENTRE POINT INY	100.000	MILLING FEED	1000	INFEED PLANE	ZE 0.000	DEPTH	T 20.000	MAX. DEPTH PER REVOLUT.	5.000	LENGTH	L 100.000	WIDTH	B 50.000	CORNER RADIUS	R 20.000	ANGLE	W 45.000	ROTATION DIRECT. (3/4)	3	APPROACH RADIUS	AR 20.000	INPOS PROG.ON/OFF(1/0)	0
DRILLING AXIS (1=X, 2=Y, 3=Z)	: Z																														
MILLING PLANE	: XY = G17																														
CENTRE POINT INX	100.000																														
CENTRE POINT INY	100.000																														
MILLING FEED	1000																														
INFEED PLANE	ZE 0.000																														
DEPTH	T 20.000																														
MAX. DEPTH PER REVOLUT.	5.000																														
LENGTH	L 100.000																														
WIDTH	B 50.000																														
CORNER RADIUS	R 20.000																														
ANGLE	W 45.000																														
ROTATION DIRECT. (3/4)	3																														
APPROACH RADIUS	AR 20.000																														
INPOS PROG.ON/OFF(1/0)	0																														



The start is made from any position without specifying a starting angle. The starting point is calculated by the program. In all positions, a tangential approach to the outer contour **with the approach radius** is ensured.



Roughing  
or  
finishing



## Programming Example

Milling an outside frame.

```

.
.
N101   T1234       Tool number
N102   M6           Tool change
N103   M3 S500     Direction of rotation/speed
N104   GO X0 Y0    Position axes to zero
N105   D1           Call tool number from geometry table
                          (D compensation)
N106   P9990111    Call outside frame cycle
                          100, Centre point in X (mm, absolute)
                          100, Centre point in Y (mm, absolute)
                          500, Milling feed (mm/min)
                          0, Infeed plane (mm, absolute)
                          20, Depth (mm, incremental)
                          5, Maximum depth per revolution (mm, incremental)
                          200, Length (mm, incremental)
                          90, Width (mm, incremental)
                          20, Corner radius (mm, incremental)
                          20, Angle (degrees, absolute)
                          3, Direction of rotation
                          25, Approach radius (mm, incremental)
                          1] In-position programming on
N107   M5
etc.

```

## Messages / Plausibility

```


MILLING FEED <=0
DEPTH <=0
MAX. INFEEED PER REVOLUTION <=0
MAX. INFEEED PER REVOLUTION > DEPTH
LENGTH <=0
WIDTH <=0
CORNER RADIUS <=0
FALSE DIRECTION OF ROTATION
ACTIVE CUTTER RADIUS <=0
LENGTH < WIDTH
APPROACH RADIUS <= CUTTER RADIUS
IN-POSITIONING PROGRAMMING FALSE


```

5.3.3 Borehole


#1: NC: typ3osa
➔
⊘
11.06.99  
17:01:27

B: Manage/Edit ↻

<i><b>BOREHOLE</b></i>		DRILLING AXIS (1=X, 2=Y, 3=Z) : Z	MILLING PLANE : XY = G17
	CENTRE POINT INX	■ 100.000	
	CENTRE POINT INY	100.000	
	MILLING FEED	1000	
	INFEED PLANE	ZE 0.000	
	DEPTH	T 20.000	
	MAX. DEPTH PER REVOLUT.	5.000	
	DIAMETER	D 100.000	
	APPROACH RADIUS	AR 20.000	
ROTATION DIRECT. (3/4)	3		



Starting point



Roughing  
or  
finishing

## Programming Example

Milling a borehole.

```

.
.
N101   T1234       Tool number
N102   M6           Tool change
N103   M3 S500     Direction of rotation/speed
N104   GO X0 Y0    Position axes to zero
N105   D1           Call tool number from geometry table
                          (D compensation)
N106   P9990112    Call borehole cycle
                          100, Centre point in X (mm, absolute)
                          100, Centre point in Y (mm, absolute)
                          1000, Milling feed (mm/min)
                          0, Infeed plane (mm, absolute)
                          10, Depth (mm, incremental)
                          10, Maximum depth per revolution (mm, incremental)
                          100, Diameter (mm, incremental)
                          3, Direction of rotation
                          20] Approach radius (mm, incremental)
N107   M5
etc.

```

## Messages / Plausibility

```

MILLING FEED <=0
DEPTH <=0
MAX. INFEEED PER REVOLUTION <=0
MAX. INFEEED PER REVOLUTION > DEPTH
DIAMETER <=0
FALSE DIRECTION OF ROTATION
ACTIVE CUTTER RADIUS <=0
APPROACH RADIUS <= CUTTER RADIUS
APPROACH RADIUS >= HALF DIAMETER

```

### 5.3.4 Inside Circle Segment

#1: NC: typ3osa
11.06.99  
17:08:33

B: Manage/Edit

## INSIDE CIRCLE SEGMENT

DRILLING AXIS (1=X, 2=Y, 3=Z)	: Z
MILLING PLANE	: XY = G17
CENTRE POINT INX	■ 100.000
CENTRE POINT INY	100.000
MILLING FEED	1000
INFEEED PLANE	ZE 0.000
DEPTH	T 20.000
MAX.DEPTH PER REVOLUT.	5.000
DIAMETER	D 100.000
APPROACH RADIUS	AR 20.000
STARTING ANGLE	SW 0.000
MILLING ANGLE	FW 270.000
ROTATION DIRECT. (3/4)	3
RETURN TO STARTPOINT	1
0=RETURN IN G0	
1=RETURN IN G2/G3	

Roughing  
or  
finishing

## Programming Example

Milling an inside circle segment.

```

.
.
N101   T1234       Tool number
N102   M6          Tool change
N103   M3 S500     Direction of rotation/speed
N104   GO X0 Y0    Position axes to zero
N105   D1          Call tool number from geometry table
                          (D compensation)
N106   P9990113    Call inside circle segment cycle
                          100, Centre point in X (mm, absolute)
                          100, Centre point in Y (mm, absolute)
                          1000, Milling feed (mm/min)
                          0, Infeed plane (mm, absolute)
                          20, Depth (mm, incremental)
                          5, Maximum depth per revolution (mm, incremental)
                          100, Diameter (mm, incremental)
                          3, Direction of rotation
                          20, Approach radius (mm, incremental)
                          90, Starting angle (degrees, absolute)
                          180, Milling angle (degrees, absolute)
                          1] Return to starting point in G2/G3
N107   M5
etc.

```

## Messages / Plausibility

```

MILLING FEED <=0
DEPTH <=0
MAX. INFEEED PER REVOLUTION <=0
MAX. INFEEED PER REVOLUTION > DEPTH
CUTTER RAD. >= (HALF DIAMETER * 0.9)
DIAMETER <=0
FALSE DIRECTION OF ROTATION
ACTIVE CUTTER RADIUS <=0
APPROACH RADIUS <= CUTTER RADIUS
APPROACH RADIUS >= HALF DIAMETER
RETURN TO STARTING POINT FALSE
CUTTER ANGLE <=0

```

### 5.3.5 Outside Circle Segment

#1:
➡
⊘
11.06.99  
17:10:37

B: Manage/Edit
⏪

## OUTSIDE CIRCLE SEGME

DRILLING AXIS (1=X, 2=Y, 3=Z)	: Z
MILLING PLANE	: XY = G17
CENTRE POINT INX	100.000
CENTRE POINT INY	100.000
MILLING FEED	1000
INFEEED PLANE	ZE 0.000
DEPTH	T 20.000
MAX.DEPTH PER REVOLUT.	5.000
DIAMETER	D 100.000
APPROACH RADIUS	AR 20.000
STARTING ANGLE	SW 0.000
MILLING ANGLE	FW 270.000
ROTATION DIRECT. (3/4)	3
RETURN TO STARTPOINT	1
0=RETURN IN G0	
1=RETURN IN G2/G3	

Roughing  
or  
finishing

## Programming Example

Milling an outside circle segment.

```

.
.
N101   T1234       Tool number
N102   M6          Tool change
N103   M3 S500     Direction of rotation/speed
N104   GO X0 Y0    Position axes to zero
N105   D1          Call tool number from geometry table
                    (D compensation)
N106   P9990115    Call outside circle segment cycle
                    100, Centre point in X (mm, absolute)
                    100, Centre point in Y (mm, absolute)
                    1000, Milling feed (mm/min)
                    0, Infeed plane (mm, absolute)
                    20, Depth (mm, incremental)
                    5, Maximum depth per revolution (mm, incremental)
                    200, Diameter (mm, incremental)
                    3, Direction of rotation
                    20, Approach radius (mm, incremental)
                    90, Starting angle (degrees, absolute)
                    180, Milling angle (degrees, absolute)
                    1] Return to starting point in G2/G3
N107   M5
etc.

```

## Messages / Plausibility

```

MILLING FEED <=0
DEPTH <=0
MAX. INFEEED PER REVOLUTION <=0
MAX. INFEEED PER REVOLUTION > DEPTH
CUTTER RAD. >= (HALF DIAMETER * 0.9)
DIAMETER <=0
FALSE DIRECTION OF ROTATION
ACTIVE CUTTER RADIUS <=0
APPROACH RADIUS <= CUTTER RADIUS
RETURN TO STARTING POINT FALSE
CUTTER ANGLE <=0



```

5.3.6 Tenon

#1:
➔
/
11.06.99

NC: typ3osa
/
17:05:14

B: Manage/Edit
↩

<i>TENON</i>		DRILLING AXIS (1=X, 2=Y, 3=Z) : Z																	
		MILLING PLANE : XY = G17																	
	<table style="width: 100%; border-collapse: collapse;"> <tr> <td style="padding: 2px;">CENTRE POINT INX</td> <td style="padding: 2px;">100.000</td> </tr> <tr> <td style="padding: 2px;">CENTRE POINT INY</td> <td style="padding: 2px;">100.000</td> </tr> <tr> <td style="padding: 2px;">MILLING FEED</td> <td style="padding: 2px;">1000</td> </tr> <tr> <td style="padding: 2px;">INFEEED PLANE</td> <td style="padding: 2px;">ZE 0.000</td> </tr> <tr> <td style="padding: 2px;">DEPTH</td> <td style="padding: 2px;">T 20.000</td> </tr> <tr> <td style="padding: 2px;">MAX. DEPTH PER REVOLUT.</td> <td style="padding: 2px;">5.000</td> </tr> <tr> <td style="padding: 2px;">DIAMETER</td> <td style="padding: 2px;">D 100.000</td> </tr> <tr> <td style="padding: 2px;">APPROACH RADIUS</td> <td style="padding: 2px;">AR 20.000</td> </tr> <tr> <td style="padding: 2px;">ROTATION DIRECT. (3/4)</td> <td style="padding: 2px;">3</td> </tr> </table>	CENTRE POINT INX	100.000	CENTRE POINT INY	100.000	MILLING FEED	1000	INFEEED PLANE	ZE 0.000	DEPTH	T 20.000	MAX. DEPTH PER REVOLUT.	5.000	DIAMETER	D 100.000	APPROACH RADIUS	AR 20.000	ROTATION DIRECT. (3/4)	3
CENTRE POINT INX	100.000																		
CENTRE POINT INY	100.000																		
MILLING FEED	1000																		
INFEEED PLANE	ZE 0.000																		
DEPTH	T 20.000																		
MAX. DEPTH PER REVOLUT.	5.000																		
DIAMETER	D 100.000																		
APPROACH RADIUS	AR 20.000																		
ROTATION DIRECT. (3/4)	3																		
 <p style="text-align: center;">Starting point</p> <p style="text-align: center;">Roughing or finishing</p>																			



## Programming Example

Milling a tenon.

```

.
.
N101   T1234       Tool number
N102   M6           Tool change
N103   M3 S500     Direction of rotation/speed
N104   GO X0 Y0    Position axes to zero
N105   D1           Call tool number from geometry table
                          (D compensation)
N106   P9990114    Call tenon cycle
                          100, Centre point in X (mm, absolute)
                          100, Centre point in Y (mm, absolute)
                          1000, Milling feed (mm/min)
                          0, Infeed plane (mm, absolute)
                          10, Depth (mm, incremental)
                          10, Maximum depth per revolution (mm, incremental)
                          200, Diameter (mm, incremental)
                          3, Direction of rotation
                          20] Approach radius (mm, incremental)
N107   M5
etc.

```

## Messages / Plausibility

```

MILLING FEED <=0
DEPTH <=0
MAX. INFEEED PER REVOLUTION <=0
MAX. INFEEED PER REVOLUTION > DEPTH
DIAMETER <=0
FALSE DIRECTION OF ROTATION
ACTIVE CUTTER RADIUS <=0
APPROACH RADIUS <= CUTTER RADIUS

```

Notes:

## 6 Technology parameters

The following parameters can be defined in block 1 of cycle P9990100.

These parameters determine the technology of the available milling cycles and should only be modified when required.


### 6.1 Overlap Factor (#CCVL)

This parameter defines the size of the cutter overlap. Entering 0.1 means 10% overlap of the cutter radius.

For example, if you choose a milling cutter with diameter = 20mm, specifying #CCVL= 0.1 would produce an overlap of 1mm.

$$[ ( D/2 ) * \#CCVL = 10\text{mm} * 0.1 = 1\text{mm} ]$$

BASIC VALUE = 0.1




## 6.2 Safety Clearance (#CCVS)

This parameter is used in two ways in the milling cycles. An input of 1 is equivalent to 1 mm (incremental).

### 6.2.1 Reverse Rapid Traverse


In accordance with the value entered for #CCVS, the rapid traverse travel of the infeed axis is reversed before reaching the infeed plane.



### 6.2.2 Partial Retraction

If there are several depth infeeds, after machining one depth the infeed axis is partially retracted in accordance with the value entered for #CCVS.

BASIC VALUE = 1 mm




### 6.3 Wall Clearance during Base Finishing (#CCVW)

During base finishing, the cutter must not touch the roughed wall for technological reasons.

An input of 0.01 is equivalent to 0.01 mm (incremental).

For example, if you specify #CCVW = 0.01, the cutter will remain 0.01 mm clear of the wall during base finishing.

BASIC VALUE = 0.01




### 6.4 Base Clearance during Wall Finishing (#CCVB)

During wall finishing, the cutter must not touch the finished base for technological reasons.

An input of 0.01 is equivalent to 0.01 mm (incremental).

For example, if you specify #CCVB = 0.01, the cutter is retracted 0.01 mm from the base after finishing the base.

BASIC VALUE = 0.01



Notes:

## 7 Installing the machine cycles

### 7.1 Installation

The dialogues and milling cycles/hole patterns are stored as separate files on CD-ROM.

The Typ3 osa cycle package "B\_m\_zyk.exe" contains zipped files for the following CPL cycles:

- Drilling cycles
- Drilling pictures
- Milling cycles
- Contour milling cycles

1. For installation of the cycles it is necessary to copy the file 'B\_m\_zyk.exe' in any directory of the Typ3 osa panel hard disk.

The unzipping of the files takes place automatically into these directories, which are needed for the execution of the cycles.

After installation on the Typ3 osa PC panel the directory 'c:\typ3pcp\cncfiles\rbzyklen' is generated. In this directory all necessary files are copied.

The used BMP files are copied into the directory 'c:\typ3pcp\bin\cplbmp'

2. Terminate all running "Typ3 osa"-application files.  
Mount the PC directory 'c:\typ3pcp\cncfiles' for the control. This can be carried out with the Typ3 osa tool 't3config.exe'. Start afterwards the Typ3 osa application files again.

3. The file 'cpdlg05.dlg' (call of the main program) must be copied into the control-root directory or user-FEPROM.

The file 'cpdlg05.dlg' is located in the mount directory 'c:\typ3pcp\cncfiles\rbzyklen' of the PC panel (for copying into the OM (Operating mode) 'Manage' change via soft keys (SK's) 'switch Directory' and 'Subdirectory (+)' into the subdirectory 'rbzyklen').

4. The files, depending on the language 'Zyktex.te.049', and 'Zyktex.te.044' must be copied into the user-FEPROM (directory '/usrfep'). The files (e.g. 'Zyktex.te.049') is always located in the mounted directory 'c:\typ3pcp\cncfiles\rbzyklen' of the operating panel.

5. All further files have to be stored in a directory, which is a directory for subprograms (compare parameterblock 308000001), or the MACODA parameterblock 308000001 has to be adapted accordingly. The parameterblock 308000001 fixes the sequence of the searching criterias for the CPL-cycles.

Example: Parameterblock 308000001: Searching path for subprograms

```
Parameter 0 .
    1 /usr/
    2 user
    3 mtb
    4 Bosch
    5 /usrfep
    6 /feprom
    7 /mnt/rb>
    8 zyklen
    9
```

6. With the program 'Linken.cpl' it is possible to generate all necessary linktables. The program must only be started in the first channel. The programmexecution is protocolled in the file 'Linken.log'.

## 7.2 Installed programs

Installed CPL-Programs in the directory 'c:\typ3pcp\cncfiles\rbzyklen':

### Mainprograms

- Hauptdlg.dlg Overview over the Bosch standard cycles
- Bohrbild.dlg Mainprogram and overview over drilling pictures
- Bohren.dlg Mainprogram and overview over drilling cycles
- Kontur.dlg Mainprogram and overview over contour-milling cycles
- Taschen.dlg Mainprogram and overview over milling cycles
- Readme.txt Info-file for installation of the Bosch standard cycles

### Subprograms

- Bohrachs.rb Subprogram for viewing and definition of the drilling axis
- CPL\_Rahmen.rb Subprogram for drawing of CPL grafic frame
- check\_NK Subprogram for elimination of non used digits behind the comma
- RB\_Zyklen.ini Subprogram for initialization of text and colors
- 999999194 Subprogram for drawing
- 999999195 Subprogram for drawing
- 999999196 Subprogram for drawing
- 999999197 Subprogram for drawing
- 999999198 Subprogram for drawing
- 999999199 Subprogram for drawing



### Direct program calls from CPL dialog programs


- ZYK\_G81 CPL-dialog program for drilling cycle G81
- ZYK\_G82 CPL-dialog program for drilling cycle G82
- ZYK\_G83 CPL-dialog program for drilling cycle G83
- ZYK\_G84 CPL-dialog program for drilling cycle G84
- ZYK\_G85 CPL-dialog program for drilling cycle G85
- ZYK\_G86 CPL-dialog program for drilling cycle G86
- ZYK\_G184 CPL-dialog program for drilling cycle G184
- ZYK\_102 CPL-dialog program for pocket milling cycle 'rectangular pocket'
- ZYK\_103 CPL-dialog program for pocket milling cycle 'circular pocket'
- ZYK\_104 CPL-dialog program for pocket milling cycle 'groove'
- ZYK\_106 CPL-dialog program for pocket milling cycle 'end groove'
- ZYK\_110 CPL-dialog program for contour pocket 'inside frame'
- ZYK\_111 CPL-dialog program for contour-milling cycle 'outside frame'
- ZYK\_112 CPL-dialog program for contour-milling cycle 'borehole'
- ZYK\_113 CPL-dialog program for contour-milling cycle 'inside circle segment'
- ZYK\_114 CPL-dialog program for contour-milling cycle 'tenon'
- ZYK\_115 CPL-dialog program for contour-milling cycle 'outside circle segment'
- ZYK\_150 CPL-dialog program for hole series
- ZYK\_151 CPL-dialog program for hole circles
- ZYK\_152 CPL-dialog program for hole grid

### Auxiliary programs

- Linken.cpl Create link- and sublink tables
- Linkliste.txt Data file for the program 'Linken.cpl'


### 7.3 Adaption of MACODA datas

1. Parameterblock 909800002: Amount of channels  
The input value has to be 1 higher than requested amount of channels.  
**Example:** 4 useable channels → Input value = 5

 **For creating this parameter the user-identification has to be not identical with 'Endanwender'.**

2. Parameterblock 308000005: CPL-dialog-channel  
In this channel all programs are executed, which are started with Softkey 'CPL-Dialog'.  
**Example:** 4 → CPL dialog programs start in 4. channel

3. Parameterblock 308000003: Data areas for CPL-programs
  - Parameter 0: 6144 (Stack)
  - Parameter 1: 65000 (Link tables)

 **This parameter is a channel dependant parameter. The adjustment has to be according to CPL-dialog-channel (parameterblock 308000005). After selection of this parameterblock you are in 'System Control Reset' and you can select by Softkey 'next channel' the CPL-dialog-channel for the changes.**

4. Parameterblock 308000006: Selection of cycle name and CPL-dialog-program

#### List with cycle names:

Parameter	Value
0	G81
1	G82
2	G83
3	G84
4	G85
5	G86
6	G184
7	P9990102
8	P9990103
9	P9990104
10	P9990106
11	P9990110
12	P9990111
13	P9990112
14	P9990113
15	P9990114
16	P9990115
17	P9990150
18	P9990151
19	P9990152

 **After the next start up of the control the changes of MACODA values are activated.**

5. Parameterblock 308000007: Selection of cycle name and CPL-dialog-program

**List of the CPL-dialog-programs:**

Parameter	Value
1	ZYK_G82
2	ZYK_G83
3	ZYK_G84
4	ZYK_G85
5	ZYK_G86
6	ZYK_G184
7	ZYK_102
8	ZYK_103
9	ZYK_104
10	ZYK_106
11	ZYK_110
12	ZYK_111
13	ZYK_112
14	ZYK_113
15	ZYK_114
16	ZYK_115
17	ZYK_150
18	ZYK_151
19	ZYK_152

 **After the next start up of the control the changes of the MACODA values are activated.**

## 7.4 Troubleshooting

Possible reasons for failors:

1. Part program failor 452: 'Too less storage for program'  
Part program failor 465: 'Too less storage for program'  
**Remedy:** Parameter block 308000003 increase parameter 'Linktabellen' for CPL-dialog-channel.
2. Part program failor 782: 'No runtime memory available'  
**Remedy:** Parameterblock 308000003 increase parameter 'Stack' for CPL-dialog-channel.
3. Part program failor 739: 'No empty CPL window available'  
**possible reason:** Application 'CPL-Dialog' not yet started.'CPL-Dialog' allready started, e.g. from a different channel.
4. Part program failor 1502: 'Unzulaessiger Dateiname. -> RB\_Zyklen.ini'  
**possible reason:** The language depending text file is not available in user-FEPROM.  
**Remedy:** Copy text file, e.g. 'Zyktexte.049' into user-FEPROM.
5. Part program failor137: 'File is protected. -> RB\_Zyklen.ini'  
**possible reason:** The language depending text file has no reading access.  
**Remedy:** Set access rights for text file.
6. CPL-dialog-program does not start, even the softkey is available in editor  
**possible reason:** The CPL-dialog-channel value is bigger, than the amount of channels in the system.  
**Remedy:** Check the parameterblocks 308000005 und 909800002.  
Example: 308000005 = 4, CPL-dialog opertates in channel 4  
909800002 = 5, system contains 4 channels
7. Softkey 'CPL-Dialog' not available in the editor  
**possible reason:** The file 'cpldlg05.dlg' is neither available in the root directory nor in the user-FEPROM.  
**Remedy:** Copy file in root directory or user-FEPROM.
8. MACODA-Block 909800002 is missing in the block selection box.  
**possible reason:** The user-identification is equal 'Enduser'.  
**Remedy:** Set the user-identification non equal 'Enduser' (set GOM Diagnostics,Install,Macoda,Organise,User).

# A Appendix

## A.1 Index

### A

Adaption of MACODA datas, 7–4  
 Angle  
   Groove, 3–9  
   Rectangular Pocket/Inside Frame/Outside Frame, 3–9  
 Approach Radius  
   Borehole, 3–20  
   Inside Circle Segment, 3–22  
   Outside Circle Segment, 3–22  
   Inside Frame, 3–21  
   Outside Frame, 3–21  
   Tenon, 3–20

### B

Base Clearance during Wall Finishing, 6–3

### C

Centre Point  
   Plane G17, 3–2  
   Plane G18, 3–2  
   Plane G19, 3–2  
 Contour Milling Cycle Menu, 5–3  
 Contour Milling Cycles  
   Borehole, 5–16  
   Inside Circle Segment, 5–18  
   Outside Circle Segment, 5–20  
   Inside Frame, 5–12  
   Outside Frame, 5–14  
   Tenon, 5–22  
 Corner Radius, 3–8  
   Rectangular Pocket/Inside Frame, 3–8  
   Rectangular Pocket/Outside Frame, 3–8  
 Cutter Compensation, 4–1  
 Cutter Radius, 4–1

### D

Deactivation conditions, 2–2  
 Depth, 3–5  
 Description of cycles, 5–1  
 Diameter  
   Circular Pocket/Borehole, 3–10  
   End Groove/Inside Diameter/Outside Diameter, 3–10  
   Inside Circle Segment, 3–11  
   Outside Circle Segment, 3–11  
   Tenon, 3–10  
 Direction of Rotation, 3–12  
   during Mirroring, 3–13  
 Documentation, 1–7  
 Down/Up Milling, 3–12

### E

EMC Directive, 1–1  
 EMERGENCY–STOP devices, 1–5  
 ESD, Electrostatic discharge, 1–5  
 ESD–sensitive components, 1–5, 1–6

### F

Feed  
   Drilling Feed, 3–3  
   Roughing Feed, 3–3  
   Finishing Feed, 3–3  
   Milling Feed, 3–3  
 Infeed Plane, 3–4  
 Blank Overmeasure  
   Circular Pocket, 3–16  
   Rectangular Pocket, 3–16  
   Groove, 3–16  
 Finishing Overmeasure/Base  
   Circular Pocket, 3–15  
   Rectangular Pocket, 3–15  
   Groove, 3–15  
 Finishing Overmeasure/Wall  
   Circular Pocket, 3–14  
   Rectangular Pocket, 3–14  
   Groove, 3–14

### I

In–position Programming, 3–24  
 Infeed Axis and Direction, 4–1  
 Installed programs, General, 7–2  
 Installing the machine cycles, 7–1  
   Installation, 7–1

### L

Length/Width  
   Groove, 3–7  
   Rectangular Pocket/Inside Frame, 3–7  
   Rectangular Pocket/Outside Frame, 3–7  
 Low–Voltage Directive, 1–1

### M

Main Menu, 5–1  
 Max. Depth per Revolution, 3–6  
 Menu Overview, 5–1  
 Milling Angle  
   Inside Circle Segment, 3–23  
   Outside Circle Segment, 3–23  
 Milling Plane, 4–1  
 Modifications, 1–7

Modules sensitive to electrostatic discharge. *See* ESD-sensitive components

**P**

Pocket Milling Cycle Menu, 5-2

Pocket Milling Cycles

    Circular Pocket, 5-6

    Groove, 5-8

    End Groove, 5-10

    Rectangular Pocket, 5-4

Proper use, 1-1

**Q**

Qualified personnel, 1-3

**R**

Return to Starting Point, 3-24

Roughing/Finishing, 3-1

    Combined, 3-1

    Finishing, 3-1

    Roughing, 3-1

**S**

Safety instructions, 1-4

Safety markings, 1-4

Scale Factor, 4-1

Spare parts, 1-5

Special Features, 2-1

Spindle

    Direction of Rotation, 4-1

    Speed, 4-1

Starting Angle

    Borehole, 3-18

    End Groove, 3-17

    Inside Circle Segment, 3-17

    Inside Frame, 3-19

    Outside Circle Segment, 3-17

    Tenon, 3-18

    Tenon (Frame), 3-19

**T**

Technology parameters, 6-1

    Overlap Factor, 6-1

    Partial Retraction, 6-2

    Reverse Rapid Traverse, 6-2

    Safety Clearance, 6-2

Tool, 4-1

Trademarks, 1-8

Troubleshooting, 7-6

**V**

Version, 1-7

**W**

Wall Clearance during Base Finishing, 6-3

# Bosch-Automationstechnik

Robert Bosch GmbH  
Geschäftsbereich  
Automationstechnik  
Industriehydraulik  
Postfach 30 02 40  
D-70442 Stuttgart  
Telefax (07 11) 8 11-18 57

Robert Bosch GmbH  
Geschäftsbereich  
Automationstechnik  
Fahrzeughydraulik  
Postfach 30 02 40  
D-70442 Stuttgart  
Telefax (07 11) 8 11-17 98

Robert Bosch GmbH  
Geschäftsbereich  
Automationstechnik  
Pneumatik  
Postfach 30 02 40  
D-70442 Stuttgart  
Telefax (07 11) 8 11-89 17

Robert Bosch GmbH  
Geschäftsbereich  
Automationstechnik  
Montagetechnik  
Postfach 30 02 07  
D-70442 Stuttgart  
Telefax (07 11) 8 11-77 77

Robert Bosch GmbH  
Geschäftsbereich  
Automationstechnik  
Antriebs- und Steuerungstechnik  
Postfach 11 62  
D-64701 Erbach  
Telefax (0 60 62) 78-4 28

Robert Bosch GmbH  
Geschäftsbereich  
Automationstechnik  
Schraub- und Einpreßsysteme  
Postfach 11 61  
D-71534 Murrhardt  
Telefax (0 71 92) 22-1 81

Robert Bosch GmbH  
Geschäftsbereich  
Automationstechnik  
Entgratetechnik  
Postfach 30 02 07  
D-70442 Stuttgart  
Telefax (07 11) 8 11-34 75

Robert Bosch GmbH  
Geschäftsbereich  
Automationstechnik  
Schulung AT/VSZ  
Berliner Straße 25  
D-64711 Erbach  
Telefax (0 60 62) 78-8 33

Technische Änderungen vorbehalten

Ihr Ansprechpartner

# BOSCH



Robert Bosch GmbH  
Geschäftsbereich  
Automationstechnik  
Antriebs- und Steuerungstechnik  
Postfach 11 62  
D-64701 Erbach  
Telefax (0 60 62) 78-4 28

Begleitakte für:  
Typ3 osa

# Universal Milling Cycles

## 1070 073 795-101 (99.07) GB

Erstausgabe	⊗	Produktbetreuer	Prößdorf
Überarbeitung	○	erstellt mit	Interleaf
Übersetzung	⊗	angelegt am	21.07.99
Autor	Grohmann	Seiten	80

Aufgabe	Mitarbeiter	Datum
Bestellnummer anlegen oder Index erhöhen		
In Budgetplan aufnehmen		
<b>Konzept vom Dienstleister erhalten</b>		
Korrektorexemplare vom Dienstleister erhalten		
Korrektorexemplar an AT/VTs	Rückgabetermin:	
Korrektorexemplar an AT/ENC	Rückgabetermin:	
Korrektorexemplar an AT/VSZ	Rückgabetermin:	
Korrektorexemplar an AT/VKS	Rückgabetermin:	
Korrektorexemplar an ErB/QSG6	Rückgabetermin:	
Korrektorexemplar an	Rückgabetermin:	
Abnahmeprotokoll von AT/VTs zurück		
Abnahmeprotokoll von AT/ENC zurück		
Abnahmeprotokoll von AT/VSZ zurück		
Abnahmeprotokoll von AT/VKS zurück		
Abnahmeprotokoll von ErB/QSG6 zurück		
Abnahmeprotokoll von zurück		
Korrektorexemplar geprüft		
Korrekturen im Original eingearbeitet / mit Dienstleister besprochen		
Original vom Dienstleister erhalten und Datei abgelegt		
<b>An Übersetzer</b>		
An Übersetzer	Rückgabetermin:	
Übersetzung zurück und Datei ablegen		
<b>Original fertig</b>		
Bestellnummer im SAP anlegen, Deutsch und Englisch		
<b>Freigabe bei TEF10 beantragen</b>		
TEF10 muß Index im Kurztext erhöhen		
Datei an TEF10 übergeben		
Archivierung abgeschlossen		
<b>Original mit Druckfreigabe an VSZ45</b>		
Im Monatsbericht eintragen		
In Dokuliste-Neu mit Korrekturbalken eintragen		
Abschließend im BudgetPlan eintragen		
In Zielentfaltungstatistik eintragen		
Datei im Archiv-Verzeichnis ablegen		
IDU im Freigabe-Verzeichnis ablegen		
IDU für PDF an ProLeaf		
Belegexemplare von VSZ45 erhalten		
Verteilt, e-mail		
Korrektur-/Büroexemplar ablegen		
Vorgängerausgabe im Archivschrank ablegen		
PDF für Intranet bereitstellen		

Bemerkungen: